T N Buckman

Office Memo

TO: File

FROM: Gary F. Kulibert

SUBJECT: Lehrer's Landfill Site

DATE: September 7, 1976

8-24-76

At the time of the inspection it appeared that the landfill site was being operated in conformance with the Codes. The abandonment of adjacent site areas appeared to be acceptable. Erosion did not appear to be a serious problem at this time.

GFK

Gary F. Kulibert

GFK:jh

01032

Tn. Buchanan - Outagamie Co. L.F.

OFFICE MEMO

September 7, 1976

SUBJECT: Lehrer Landfill - Kaukauna, Wisconsin → FILE SOLID WASTE

FROM: Terrence L. Gardon

On August 31, 1976, I inspected the Lehrer landfill located in Kaukauna, Wisconsin at approximately 6:30 a.m. At that time all refuse from the previous day was adequately covered. One load of refuse had been deposited in the fill area already that morning. A compactor tractor was working in the fill at the time.

Terrence L. Gardon

Terrence L. Gardon
Natural Resource Technician

TLG:sh

01031

ENTITY Lehrer Landfill In Buchanan FILE COUNTY Out.

EVALUATION	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO
1. Acceptable Sign Posted?	✓		✓		✓		✓		✓		✓		✓													
2. Adequate Screening Present?	✓		✓		✓		✓		✓		✓		✓													
3. Acceptable Gate Present?	✓		✓		✓		✓		✓		✓		✓													
4. Attendant In Accordance?	✓		✓		✓		✓		✓		✓		✓													
5. Insects & Rodents Controlled?	✓		✓		✓		✓		✓		✓		✓													
6. Windblown Material Controlled?	✓	✓	✓		✓		✓		✓		✓		✓													
7. Active Area Confined?	✓		✓		✓		✓		✓		✓		✓													
8. All-Weather Roads Provided?	✓		✓		✓		✓		✓		✓		✓													
9. C & C Appear Adequate?	✓		✓			✓		?	✓		✓		✓													
10. Surface Water Diverted?	✓		✓		✓		✓		✓		✓		✓													
11. Leachate Absent Or Controlled?		✓	✓		✓		✓		✓		✓		✓													
12. Unauthorized Wastes Absent?	✓		✓		✓		✓		✓		—		✓													
13. Open Burning In Accordance?	✓		✓		✓		✓		✓		✓		✓													
14. Adequate Firebreaks Present?	✓		✓		✓		✓		✓		✓		✓													
15. Date & Time Of Inspection	9-3-76 11:15a		10-18-76 11:00		11:20 12-16-76		1/31/77		12:10 2-28-77		12:00 5-15		6-2-77													

COMMENTS: Leachate streams present 9-3-76

12-16-76 Poor covering, site did not look open. Could not see gate

5-15-77 Much surface water in ditch

6-2-77 Dumping refuse in surface water in trench.

00837

24

T N Buchanan
Lehrer

OFFICE MEMO

September 2, 1976

FROM: Gary F. Kulibert

SUBJECT: Lehrer's Landfill

I have reviewed the Soil Testing Service of Wisconsin report on the proposed Lehrer landfill site located in Kaukauna, Wisconsin. Based on my review it appears that the site does have potential for development as a landfill site. There is adequate clays overbed rock which would eliminate any potential contamination of ground water in this area. However, while investigating a recent complaint I feel the plans have failed to indicate a unique situation on the north end of the landfill site. This is especially true considering that the topography does not extend in that direction. Recently we inspected a complaint and found leachates seeping from the side of a hill approximately 250 feet north of the present active area. Conductivity reading was taken which indicated better than 200 µMHOS. In talking to residents in the area apparently ~~and~~ an old ravine had been filled with refuse and then covered. These leachate seeps began after Mr. Lehrer began excavating and disposing in ~~this~~ the present area. I feel this problem must be addressed both in the hydrageologic study as well as the re-engineering.

Besides the above-mentioned problem I do not foresee where the site, if properly operated, will contribute significantly to any environmental degradation.

Gary F. Kulibert

Gary F. Kulibert

GFK:sh

01030